

Passande skruvmejsel för olika skruvar



Maskinskruv



Raka spår

Mejseltjocklek x mejselbredd mm	För Metrisk skruvar M				För Unified skruvar UNC		
	MCS 	MSCS 	MFS 	MKFS 	ULCS 	UFS 	UKFS 
0,4x2,5	M 1,6	M 1,6	M 1,6	M 1,6	—	—	—
0,5x3 (0,5x3,5)	M 2	M 2	M 2	M 2	—	—	—
0,6x3,5 (0,6x4)	M 2,5	M 2,5	M 2,5	M 2,5	—	—	—
0,8x4 (0,8x5,5)	M 3	M 3	M 3	M 3	Nr 5	Nr 5	Nr 5
1,0x5,5 (1,0x6,5)	M 3,5	M 3,5	M 3,5	M 3,5	Nr 6, 8	Nr 6, 8	Nr 6, 8
1,2x6,5	M 4	M 4	M 4	M 4	Nr 10, 12	Nr 10, 12	Nr 10, 12
1,2x8	M 5	M 5	M 5	M 5	—	—	—
1,6x10	M 6	M 6	M 6	M 6	1/4	1/4	1/4
2,0x12 (2x13)	M 8	M 8	M 8	M 8	5/16, 3/8, 1/2	5/16, 3/8, 1/2	5/16, 3/8, 1/2
2,5x14 (2,5x16)	M 10	M 10	M 10	M 10	5/8, 3/4	5/8, 3/4	5/8, 3/4

Mejseldimensioner inom parentes avser äldre standard.



Kryss-spår (Phillips och Pozidriv/Supadriv)

Kryss-spår nr	För Metrisk skruvar M			För Unified skruvar UNC		
	MRX 	MFX 	MFKX 	URX 	UFX 	UKFX 
0	M 1,6 M 2	M 1,6 M 2	M 1,6 M 2			
1	M 2,5 M 3	M 2,5 M 3	M 2,5 M 3			
2	M 3,5 M 4 M 5	M 3,5 M 4 M 5	M 3,5 M 4 M 5	Nr 5 Nr 6 Nr 8 Nr 10	Nr 5 Nr 6 Nr 8 Nr 10	Nr 5 Nr 6 Nr 8 Nr 10
3	M 6	M 6	M 6	Nr 12 1/4	Nr 12 1/4	Nr 12 1/4
4	M 8 M 10	M 8 M 10	M 8 M 10	5/16 3/8 7/16 1/2	5/16 3/8 7/16 1/2	5/16 3/8 7/16 1/2