

(Forts) Gängpressande skruv

 Raka spår	För ST-gångor	
	CSK CSS	KFSK KFSS
Mejseltjocklek× mejselbredd mm		
0,4×2,5	—	—
0,5×3 (0,5×4)	ST 2	ST 2.2
0,6×3,5 (0,6×4)	—	—
0,8×4 (0,8×5,5)	ST 2.9	ST 2.9
1,0×5,5 (1,0×6,5)	ST 3	ST 3.5
1,2×6,5	ST 4.2 ST 4.8	ST 4.2 ST 4.8
1,8×8	—	—
1,6×8	—	—
1,6×10	ST 5.5 ST 6.3	ST 5.5 ST 6.3
2×12 (2×13)	ST 8	ST 8
2,5×14 (2,5×16)	ST 9.5	ST 9.5

 Kryss-spår	För ST-gångor	
	RXK RXS	KFX KFXS
(Phillips och Pozidriv/Supadriv)		
0	ST 2.2	ST 2.2
1	ST 2.9	ST 2.9
2	ST 3.5 ST 4.2 ST 4.8	ST 3.5 ST 4.2 ST 4.8
3	ST 5.5 ST 6.3	ST 5.5 ST 6.3
4	ST 8 ST 9.5	ST 8 ST 9.5

Träskruv

 Raka spår	För DIN-skruv			För SMS-skruv		
	TKS	TFS	TKFS	TKS	TFS	TKFS
	 DIN 96	 DIN 97	 DIN 95	 SMS —	 SMS 1573	 SMS 1574
(SMS 2830) mm	Diam. mm		Nr	Diam. mm		Nr
0,5×3	2		2	—		—
0,8×3,5	2,5 2,7		3 4	2.15		2
0,8×4	3 3,5		5 6	2.8		4
1,0×5,5	3,8 4 4,5		7 8 9	3,45		6
1,2×6,5	—		—	—		—
1,2×8	— 5 (5,5)		— 10 (12)	4,15 4,8 5,45 6,15		8 10 12 14
1,6×8	6		14	—		—
1,6×10	—		—	6,8		16
2×12	(7)		(16)	7,5		18
2,5×14	(10)		(24)	—		—

 Kryss-spår (Phillips och Pozidriv/Supadriv)	För DIN-skruv			För SMS-skruv		
	TKX	TFX	TKFX	TKX	TFX	TKFX
	 DIN 7996	 DIN 7997	 DIN 7995	 SMS —	 SMS —	 SMS —
Nr	Diam. mm		Nr	Diam. mm		Nr
0	(2)		(2)	—		—
1	2,5 3		5 5	— 2,8		— 4
2	3,5 4 4,5 5		6 8 9 10	3,45 4,15 4,8 —		6 8 10 —
3	(5,5) 6 (7)		(12) 14 (16)	5,45 6,15 6,8		12 14 16
4	(8)		18	—		—