

(Forts) Gängpressande skruv

 Raka spår	För ST-gångor	
	CSK CSS	KFSK KFSS
Mejseltjocklek× mejselbredd mm		
0,4×2,5 0,5×3 (0,5×4) 0,6×3,5 (0,6×4)	— ST 2 —	— ST 2.2 —
0,8×4 (0,8×5,5) 1,0×5,5 (1,0×6,5) 1,2×6,5	ST 2.9 ST 3 ST 4.2 ST 4.8	ST 2.9 ST 3.5 ST 4.2 ST 4.8
1,8×8 1,6×8 1,6×10	— — ST 5.5 ST 6.3	— — ST 5.5 ST 6.3
2×12 (2×13) 2,5×14 (2,5×16)	ST 8 ST 9.5	ST 8 ST 9.5

 Kryss-spår	För ST-gångor	
	RXK RXS	KFX KFXS
(Phillips och Pozidriv/Supadriv)		
0	ST 2.2	ST 2.2
1	ST 2.9	ST 2.9
2	ST 3.5 ST 4.2 ST 4.8	ST 3.5 ST 4.2 ST 4.8
3	ST 5.5 ST 6.3	ST 5.5 ST 6.3
4	ST 8 ST 9.5	ST 8 ST 9.5

Träskruv

 Raka spår	För DIN-skruv			För SMS-skruv		
	TKS	TFS	TKFS	TKS	TFS	TKFS
	 DIN 96	 DIN 97	 DIN 95	 SMS —	 SMS 1573	 SMS 1574
(SMS 2830) mm	Diam. mm		Nr	Diam. mm		Nr
0,5×3 0,8×3,5	2 2.5 2.7		2 3 4	— 2.15		— 2
0,8×4	3 3.5		5 6	2.8		4
1,0×5,5	3.8 4 4.5		7 8 9	3.45		6
1,2×6,5 1,2×8	— — 5 (5.5)		— — 10 (12)	— 4.15 4.8 5.45 6.15		— 8 10 12 14
1,6×8 1,6×10 2×12 2,5×14	6 — (7) (10)		14 — (16) (24)	— 6.8 7.5 —		— 16 18 —

 Kryss-spår (Phillips och Pozidriv/ Supadriv)	För DIN-skruv			För SMS-skruv		
	TKX	TFX	TKFX	TKX	TFX	TKFX
	 DIN 7996	 DIN 7997	 DIN 7995	 SMS —	 SMS —	 SMS —
Nr	Diam. mm		Nr	Diam. mm		Nr
0	(2)		(2)	—		—
1	2.5 3		5 5	— 2.8		— 4
2	3.5 4 4.5 5		6 8 9 10	3.45 4.15 4.8 —		6 8 10 —
3	(5.5) 6 (7)		(12) 14 (16)	5.45 6.15 6.8		12 14 16
4	(8)		18	—		—