

(Forts) Gängpressande skruv

 Raka spår	För ST-gångor	
	CSK CSS	KFSK KFSS
 Mejseltjocklek× mejselbredd mm		
0,4×2,5	—	—
0,5×3 (0,5×4)	ST 2	ST 2.2
0,6×3,5 (0,6×4)	—	—
0,8×4 (0,8×5,5)	ST 2.9	ST 2.9
1,0×5,5 (1,0×6,5)	ST 3	ST 3.5
1,2×6,5	ST 4.2 ST 4.8	ST 4.2 ST 4.8
1,8×8	—	—
1,6×8	—	—
1,6×10	ST 5.5 ST 6.3	ST 5.5 ST 6.3
2×12 (2×13)	ST 8	ST 8
2,5×14 (2,5×16)	ST 9.5	ST 9.5

 Kryss-spår	För ST-gångor	
	RXK RXS	KFX KFXS
 (Phillips och Pozidriv/Supadriv)		
0	ST 2.2	ST 2.2
1	ST 2.9	ST 2.9
2	ST 3.5	ST 3.5
	ST 4.2	ST 4.2
	ST 4.8	ST 4.8
3	ST 5.5	ST 5.5
	ST 6.3	ST 6.3
4	ST 8	ST 8
	ST 9.5	ST 9.5

Träskruv

 Raka spår	För DIN-skruv			För SMS-skruv		
	TKS	TFS	TKFS	TKS	TFS	TKFS
						
Mejseltjocklek× mejselbredd	DIN 96	DIN 97	DIN 95	SMS —	SMS 1573	SMS 1574
(SMS 2830) mm	Diam. mm	Nr		Diam. mm	Nr	
0,5×3	2	2		—	—	
0,8×3,5	2.5	3		2.15	2	
	2.7	4				
0,8×4	3	5		2.8	4	
	3.5	6				
1,0×5,5	3.8	7		3.45	6	
	4	8				
	4.5	9				
1,2×6,5	—	—		—	—	
1,2×8	—	—		4.15	8	
	5	10		4.8	10	
	(5.5)	(12)		5.45	12	
				6.15	14	
1,6×8	6	14		—	—	
1,6×10	—	—		6.8	16	
2×12	(7)	(16)		7.5	18	
2,5×14	(10)	(24)		—	—	

 Kryss-spår (Phillips och Pozidriv/Supadriv)	För DIN-skruv			För SMS-skruv		
	TKX	TFX	TKFX	TKX	TFX	TKFX
						
För kryss-spår (SMS 2831)	DIN 7996	DIN 7997	DIN 7995	SMS —	SMS —	SMS —
Nr	Diam. mm	Nr		Diam. mm	Nr	
0	(2)	(2)		—	—	
1	2.5	5		—	—	
	3	5		2.8	4	
2	3.5	6		3.45	6	
	4	8		4.15	8	
	4.5	9		4.8	10	
	5	10		—	—	
3	(5.5)	(12)		5.45	12	
	6	14		6.15	14	
	(7)	(16)		6.8	16	
4	(8)	18		—	—	